



Warwick Police Department
Incident Report

Page: 1
11/14/2019

Incident #: 19-6514-OF
Call #: 19-85040

Date/Time Reported: 11/12/2019 1144
Report Date/Time: 11/12/2019 1159
Status: No Crime Involved

Reporting Officer: Officer Gregory Johnson
Approving Officer: Sergeant Robert Hart

Signature: _____

Signature: _____

EVENTS (S)

LOCATION TYPE: Highway/Road/Alley/Street Zone: RD 338 (POST 6)
333 SANDY LN
WARWICK RI

1 Traffic Survey: NEW CROSSWALK

PERSON(S) PERSON TYPE SEX RACE AGE SSN PHONE

#	PERSON(S)	PERSON TYPE	SEX	RACE	AGE	SSN	PHONE
1	LADOUCEUR, EDGAR N 3275 POST RD WARWICK RI 02886 DOB: 07/03/1951	REPORTING PARTY	M	W	68	*****	*****

EMPLOYER: ***** . *****

CONTACT INFORMATION:

Home Phone	(Primary)	401-447-7181
Home Phone	(Primary)	401-738-2000
Home Phone		401-738-4749
Work Phone	(Primary)	401-781-9251
CallBack Number	(Primary)	401-921-5253

Refer to Traffic Survey # 2019-24

On November 13, 2019, at 8:15 a.m., Officer Johnson met with Councilman Ladouceur in the vicinity of 333 Sandy Lane. His constituents are requesting a crosswalk in the vicinity on Sandy Lane, east of Hague Road. It was reported that several neighbors, including a gentleman who is visually impaired cross Sandy Lane to attend school or church service at St. Kevin's. The pastor, Father Marciano, also is requesting a crosswalk for pedestrian safety.

Officer Johnson concurs with Councilman Ladouceur that a crosswalk is needed in this area. It is recommended that one be installed not at an intersection, but to the east of Hague Road, just east of pole #31 (on the south side) and east of the driveway for St. Kevin's Church (on the north side).

Crosswalks that are not at an intersection, need to be marked with warning signs prior to the crosswalk in both directions. Additionally, crosswalk signs are required at the crosswalk itself. Pole #31 would be an option on the east side, otherwise sign posts would have to be installed for the other three signs. Generally, parking is not an issue in this area, so additional parking restrictions are currently not deemed to be necessary.