TO THE HONORABLE CITY COUNCIL

The undersigned respectfully petitions your body for compensation for injuries or damages sustained as follows:

Please print information that pertains to your claim.
Motor Vehicle Accident ☑Pothole ☐Property Damage ☐Tax Waiver ☐Other Claimant Name: Robert M. Bolton
Address: 60 Joseph Court
City, State, Zip: Warwick, RI 02886
Telephone #: 401-524-3072
Date of incident (M/DIY) 1/9/2023 Time: 20:15 AM I PM
Description of Incident/Claim: Hit a large pothole located on Love Lane causing damage to vehicle's
under carriage and both passenger side tires.
See attached insurance estimate with supplemental.
2000
Vehicle Year: 2020 Make: BMW Model: M550Xi Odometer reading: 35635
The Pothole was located on Love Lane road.
I notified the Finance I Public Works department on(date).
The nature of my property damage is: Undercarriage and tire of right side. See repair estimate.
Additional information about Tax Waiver (include letter from Tax Collector stating adverse decision)
I request reimbursement in the amount of \$ 300.00
SIGNATURE OF CLAIMANT: VOCALE MUBBLE 1/25/23

<u>AFFIDAVIT</u>

(Petitioner Name) Robert M. Bolton , being duly sworn, deposes and states:
1. I have petitioned the City Council of the City of Warwick for compensation for losses arising from an incident which occurred on (date) 1/9/2023 as a result of (please provide brief description):
Hit a large pothole located on Love Lane causing damage to vehicle's
under carriage and both passenger side tires. See attached insurance estimate with supplemental.
Said claim was filed with the Finance Department on (date).
2. Check appropriate box or boxes:
I have not sought compensation, nor will I at any time seek compensation from any source (including, but not limited to, any insurance company) other than the City of Warwick, for any loss arising from the above-described incident, understanding for pothole claims, the maximum recovery is \$300.00 under Rhode Island General Law § 24-5-13 (b).
I have received compensation from a source or sources other than the City of Warwick, (including, but not limited to, any insurance company) in connection with this incident. The amount(s) which I received total \$ 11,902.96 ** TOTAL REPAIR COST = \$ 17,902. and the source of the other payment(s) was Insurance Company to repair facility
I am seeking, or intend to seek, compensation from a source or sources other than and/or in addition to the City of Warwick (including, but not limited to, any insurance company), for any loss arising from the above described incident. The source or sources from which I seek such other compensation is/are:
 In the event that the Warwick City Council should deny my claim, I understand that I may pursue a claim against any other party who may be liable for my loss.
I. I understand that I am not entitled to recover more than the amount of my actual loss. If the City of Warwick pays any amount to me in connection with the above described incident, and if I should receive any amounts from any source other than the City of Warwick with respect to the above described incident, I will eport such other receipt(s) to the Finance Department of the City of Warwick.
have personal knowledge of the facts aforesaid.
dignature of Claimant or its Representative Robert M Boctow Printed Name
state of Rhode Island county of Pnvidence
Subscribed and sworn to before me on this 25 day of January , 2023
(Notary Public) My Commission Expires 6/24/24
age 2 of 2

Page 2 of 2 11.2012

Danielle M. Barnard Notary Public, State of Rhode Island My Commission Expires June 24, 2024



Frank J. Picozzi Mayor

CITY OF WARWICK FINANCE DEPARTMENT 3275 POST ROAD

3275 POST ROAD WARWICK, RHODE ISLAND 02886 (401) 738-2015

February 1, 2023

Robert Bolton 60 Joseph Court Warwick, RI 02886

Dear Robert,

This letter acknowledges receipt of your claim form to the City of Warwick. Unfortunately, the claim cannot be processed at this time due to the following reason(s);

• Registration – Copy of valid RI registration. If vehicle is leased, provide a copy of lease with claimant's name.

Included is a copy of the instructions to submit a claim. Once the above information in received, your claim can be processed. If you have any questions, please call 738-2015.

Claims Administration



STATE OF RHODE ISLAND **DIVISION OF MOTOR VEHICLES**

600 New London Avenue Cranston RI 02920-3024 Web Address: WWW.DMV.RI.GOV



Date: 01/30/2023

ARDEN ENGINEERING CONSTRUCTORS LLC 505 NARRAGANSETT PARK DR PAWTUCKET, RI 02861-4323

Registration Certificate

REG NUMBER: AE400	PLATE TYPE: PASSENGER	PLATE DESIGN: OCEAN	VEHICLE TYPE: PASSENGER	DRIVERS LICENSE N/A	REG EXP DATE: 01/31/2025
YEAR: 2020	MAKE: BMW	MODEL: M550XI	BODY TYPE: SEDAN	MAJOR COLOR: BLACK # OF PASSENGERS:	MINOR COLOR: BLACK # OF CYLINDERS:
VEHICLE IDENTIFIC WBAJS7C08LBN		RENEWAL FEE: \$128.50	GROSS WEIGHT 5534 LBS	# OF PASSENGERS. 5 CCs:	8 MAX SPEED:
FUEL TYPE: GAS		CARRYING CAPACITY: N/A	N/A	N/A	N/A
REGISTERED OWNE ARDEN ENGINE 505 NARRAGAN PAWTUCKET, RI	RLEASING OWNER: CERING CONSTRUCTO SETT PARK DR [02861-4323	RS LLC	SECOND OWNER/LES	SSEE:	

- Notice: The law requires that the DMV be notified within 10 days of any change in name or address. Please visit our website to update your
- Plate Cancellation -Excise Tax: Plates must be cancelled with the DMV to ensure the vehicle is removed from the city or town tax rolls. Please retain your receipt as proof of cancellation.
- Every registration plate shall be at all times securely fastened in a horizontal position and be in a condition to be clearly legible. Validation stickers are only to be placed securely on the lower right corner of the registration plate.
- Registration Certificate shall at all times be carried in the vehicle to which it refers or shall be carried by the person driving or in control of such
- Proof of valid insurance/financial security is required as per Rhode Island General Laws § 31-47 (Motor Vehicle Reparations Act).
- It is your responsibility to renew your registration prior to theexpiration date. Failure to do so may result in the assignment of new plates.
- Failure to obtain an Emission Inspection on or before N/A will result in this vehicle being suspended.
- Any vehicle operating in excess of legal weight limits is required to have an overweight permit per Chapter 31-25 of the Rhode Island General Laws. Failure to obtain an overweight permit may result in the imposition of fines and/or other penalties.

WAITER R. CRADDOCK

Administrator

Division of Motor Vehicles

. Craddink

Warwick Police Department Call Number Printed: 01/27/2023

Page:

1

For Date: 01/09/2023 - Monday

Call Number Time Call Reason Action Priority 23-1648 2025

Phone - POT HOLE Call Taker: SJOHNST - Civilian Sabrina A Johnston Services Rendered 3

Call Closed By: KGREENE - Civilian Katie L Greene 01/09/2023 2121 Location/Address: 589 LOVE LN @ 251 CEDAR ST

Calling Party: BOLTON, ROBERT M @ 60 JOSEPH CT - WARWICK, RI 02886 401-524-3072

Race: W Sex: M Unit: P14 Officer Anthony J D'Abrosca

Disp-20:36:46 Arvd-20:46:32 Clrd-21:20:01 Location Change:

60 JOSEPH CT [Modified: 01/09/2023 2037] Vehicle:

BLK 2020 BMW 4D M550XI Reg: PC RI AE400 VIN: WBAJS7C08LBN96032 Operator: BOLTON, ROBERT M @ 60 JOSEPH CT - WARWICK, RI 02886

Owner:

ARDEN ENGINEERS RUCTORS LLC @ 505 NARRAGANSETT PARK DR - PAWTUCKET, RI 02861

Race: U Sex: U Insurance Co:

Policy No: Narrative:

large pot hole here, rp drove home and parked the car

damaged the entire passenger side and both tires

Narrative:

ch2// left message for city highway

01/09/2023 2051

Narrative:

RP HIT A LARGE POTHOLE ON LOVE LN CAUSING DAMAGE TO FRONT AND REAR WHEEL INCLUDING FLAT TIRES. NO INJURIES. CALL NUMBER PROVIDED.

CH2 WAS ADVISED POTHOLE NEEDED TO BE FILLED.

TRAVELERS - CHARTER OAK FIRE INSURANCE COMPANY (THE)

New England Claim Center (BI-011) Email Supplements: supplementrequest@travelers.com

> By phone: (888) 299-7456 PO Box 430 Buffalo, NY 14240 Phone: (800) 422-3340

Claim #: Workfile ID:

FQP7388001 e801034d

Estimate of Record

Written By: NICK MATTHEWS, License Number: 2318040, 1/13/2023 11:08:53 PM Adjuster: TULLY, MARIANNE, (508) 946-6626 Evening

Insured:

ARDEN BUILDING

COMPANIES LLC

Owner Policy #:

CT50187VTOCAP2399A4

Claim #:

FQP7388001

Type of Loss:

Collision

Date of Loss:

01/10/2023 12:00 AM

Days to Repair:

Point of Impact:

21 Undercarriage

Deductible:

1000.00

(IXI

Owner (Insured):

ARDEN BUILDING COMPANIES

LLC 505 NARRANGANSETT PARK

PAWTUCKET, RI 02861 (401) 727-3500 Business Inspection Location:

BMW OF WARWICK 1515 BALD HILL RD WARWICK, RI 02886-0000

Field

(401) 304-3222 Day

Appraiser Information:

Nrmatthe@travelers.com (401) 258-4576

Repair Facility:

BMW Of Warwick 1515 Baldhill rd Warwick, RI 02886 (401) 824-2399 Evening

VEHICLE

2020 BMW 5 Series M550i xDrive 4D SED 8-4.4L Turbocharged Gasoline Gasoline Direct Injection White

VIN:

WBAJS7C08LBN96032

Production Date:

07/2019

Interior Color:

Black

License:

AE-400

Odometer:

35661

THECHO! COIO!

DIACK

State:

RI

Condition:

Good

Exterior Color:

White

TRANSMISSION

Automatic Transmission

4 Wheel Drive

POWER

Power Steering Power Brakes

Power Windows

Power Locks

Power Mirrors

Power Mirrors Heated Mirrors

Power Driver Seat
Power Passenger Seat

Memory Package

DECORDual Mirrors

Tinted Glass Rear Power Sunshade Air Conditioning

Intermittent Wipers
Tilt Wheel

Cruise Control Rear Defogger Keyless Entry

Alarm

Message Center

Steering Wheel Touch Controls

Telescopic Wheel Heated Steering Wheel Climate Control

Navigation System
Backup Camera
Parking Sensors

Surround View Camera Intelligent Cruise FM Radio

Stereo Search/Seek

Auxiliary Audio Connection

Premium Radio Satellite Radio

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Front Side Impact Air Bags
Head/Curtain Air Bags

Positraction

Communications System Hands Free Device Blind Spot Detection Electric Glass Sunroof

SEATS

Bucket Seats Leather Seats Heated Seats Rear Heated Seats Ventilated Seats

WHEELS

20" Or Larger Wheels

PAINT

Clear Coat Paint Metallic Paint

OTHER

Traction Control Stability Control Rear Spoiler

Signal Integrated Mirrors

Workfile ID:

FQP7388001 e801034d

Estimate of Record

2020 BMW 5 Series M550i xDrive 4D SED 8-4.4L Turbocharged Gasoline Gasoline Direct Injection White

Console/Storage Wood Interior Trim

CONVENIENCE

Home Link

RADIO

AM Radio

Heads Up Display

Lane Departure Warning

ROOF

Xenon or L.E.D. Headlamps

Power Trunk/Liftgate

Estimate of Record

2020 BMW 5 Series M550i xDrive 4D SED 8-4.4L Turbocharged Gasoline Gasoline Direct Injection White

Line		Oper		Part Number	Qty	Extended Price \$		Labo		Pain
1	RADIATOR :	SUPPOR	т							
2		Repl	Under cover w/o M5 front	51757340168	1	137.94		0.3	,	
3		Repl	Skid plate steering gear w/AWD	51757363731	1	36.57				
4	EXHAUST SY	STEM		A CONTRACTOR OF THE CONTRACTOR		30.37		0.3		
5	*	R&I	R&I exhaust assy rrwd of preconverter				m	Incl.	М	
6	WHEELS					-	****			
7		Repl	Wheel, alloy 20" style 668m, 9x20"	36117855088	1	987.00	m	0.3	М	
8		Repl	Wheel, alloy 20" style 668m, 8x20"	36117855087	1	898.00	m	0.3	М	
9	#		Mount/Balance		2	70.00	V			
10	#		Michelin Pilot 20"		1	70.00	X			
11	#		Michelin Pilot 20" Rear		1	507.06		Incl.		
12	#		Alignment		1	518.82	v	Incl.		
13	FRONT SUSP	ENSION			1	169.85	X			
14		Repl	RT Lower cntrl arm nut outer	33306787062		5.44				
15	REAR SUSPE	NSION		33300767002	1	5.14				
16			O/H rr susp rt					200		
17		Repl	RT Hub assy	33406899174		254.60	m	5.1	М	
18		Repl	Susp crossmember 530i, 540i, 540d, M550i	33316861201	1	351.60 2,124.43		Incl. 8.2	М	
19		Repl	RT Trailing arm	22206002520						
20			Deduct for Overlap	33306893528	1	171.64	m	Incl.		
21			RT Ft lateral arm	22224047520				-0.3	М	
22			RT Rr lateral arm w/o M5	33326867538	1	416.88		Incl.		
23			Deduct for Overlap	33326861126	1	196.17	m	Incl.		
24			RT Lower cntrl arm w/o M5	22225075404				-0.3	M	
25			Deduct for Overlap	33326875104	1	485.50	m	Incl.		
26			RT Upper cntrl arm	22025222				-0.3	M	
7			Deduct for Overlap	33326883340	1	588.52	m	Incl.		
8	#		clip					-0.3	Μ	
9	#		hex bolt		1	2.57		Incl.		
0	#		screw		2	30.20		Incl.		
1	#		nut		2	8.08		Incl.		
2	#		eccentric bolt		1	3.80		Incl.		
3	#		crescent		2	32.34		Incl.		
4	#		nex nut		2	13.48		Incl.		
	#		nex bolt		3	19.14		Incl.		
	#		nex bolt		1	18.45		Incl.		
	#				1	12.03		Incl.		
	#		orx bolt 07119908024		1	6.31		Incl.		
,	π	r	nex		2	7.86		Incl.		

Workfile ID:

FQP7388001 e801034d

Estimate of Record

				SUBTOTALS		8,006.28	13.3	0.0
70		Repl	RT Front brace	31106861142	1	65.68	Incl.	
40		Donl	DT Front have		-	141.44	IIICI.	
39	*	Repl	RT Upper support	33506866272	1	121.22	Incl.	
020 BI	MW 5 Series	M550i xDrive	e 4D SED 8-4.4L Turbocharged G	asoline Gasoline Direct Injection	White			

NOTES

Prior Damage Notes: none to be seen

ESTIMATE TOTALS

Category	Basis		Rate	Cost \$
Parts				7,766.43
Body Labor	0.6 hrs	@	\$ 50.00 /hr	30.00
Mechanical Labor	12.7 hrs	@	\$ 170.00 /hr	2,159.00
Miscellaneous			¥ 170.00 /III	239.85
Subtotal				10,195.28
Sales Tax	\$ 7,766.43	@	7.0000 %	543.65
Total Cost of Repairs	1 1/1 55.10		7.0000 70	10,738.93
Deductible		-		
Total Adjustments				1,000.00
				1,000.00
Net Cost of Repairs	- 1			9,738.93

All supplements must be pre-approved by Travelers.

Supplement repair charges may be subject to rejection unless approved by Travelers prior to repairs.

This instrument is a damage estimate only and not an acceptance of liability or authorization to repair.

Repair must be pre-authorized by the vehicle owner.

Vehicle owner maintains the right to repair vehicle at a repair facility of their choice.

Please present this estimate to the repair facility prior to repairs.

Necessary Information for Photograph and Video Estimates (READ CAREFULLY):

This estimate may have been completed based wholly or in part using photographs and/or video. Because of the use of photographs and video, this estimate may not be complete, as there could be hidden damage. You should provide this estimate to the shop of your choice prior to commencement of work. If your shop finds additional damages or undiscovered damages, Travelers will work with your repairer to assess the appropriate scope of work. Your shop is instructed in this estimate to contact Travelers through its supplement process and the damages they discover must be reviewed and approved prior to repairing the vehicle In the event that you are not repairing your vehicle and believe that our estimate does not account for all of your damages, please contact your Claim professional to discuss and address your concerns and options.

Workfile ID:

FQP7388001 e801034d

Estimate of Record

2020 BMW 5 Series M550i xDrive 4D SED 8-4.4L Turbocharged Gasoline Gasoline Direct Injection White

PURSUANT TO RHODE ISLAND LAW, THE CONSUMER HAS THE RIGHT TO CHOOSE THE REPAIR FACILITY TO COMPLETE REPAIRS TO A MOTOR VEHICLE; AND AN INSURANCE COMPANY MAY NOT INTERFERE WITH THE CONSUMER'S CHOICE OF REPAIRER.

FOR ANY VEHICLE THAT IS LESS THAN FORTY-EIGHT (48) MONTHS BEYOND THE DATE OF MANUFACTURE, RHODE ISLAND LAW ENTITLES THE VEHICLE OWNER TO ORIGINAL EQUIPMENT MANUFACTURER (OEM) PARTS IN THE REPAIR OF A MOTOR VEHICLE PART. THIS ESTIMATE WILL INDICATE IF/WHEN AFTERMARKET BODY PARTS ARE SPECIFIED.

Any person who knowingly presents a false or fraudulent claim for payment of a loss or benefit or knowingly presents false information in an application for insurance is guilty of a crime and may be subject to fines and confinement in prison.

Workfile ID:

Estimate of Record

2020 BMW 5 Series M550i xDrive 4D SED 8-4.4L Turbocharged Gasoline Gasoline Direct Injection White

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide ERE1952, CCC Data Date 01/03/2023, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2023 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.


OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.





Frank J. Picozzi Mayor

CITY OF WARWICK FINANCE DEPARTMENT 3275 POST ROAD WARWICK, RHODE ISLAND 02886 (401) 738-2015

February 1, 2023

Robert Bolton 60 Joseph Court Warwick, RI 02886

Dear Robert,

This letter acknowledges receipt of your claim form to the City of Warwick. Unfortunately, the claim cannot be processed at this time due to the following reason(s);

• Registration – Copy of valid RI registration. If vehicle is leased, provide a copy of lease with claimant's name.

Included is a copy of the instructions to submit a claim. Once the above information in received, your claim can be processed. If you have any questions, please call 738-2015.

Claims Administration



TRAVELERS - CHARTER OAK FIRE INSURANCE COMPANY (THE)

New England Claim Center (BI-011) Email Supplements: supplementrequest@travelers.com

By phone: (888) 299-7456 PO Box 430 Buffalo, NY 14240 Phone: (800) 422-3340

Claim #: Workfile ID:

FQP7388001 e801034d

Supplement of Record 1 with Summary

Written By: NICK MATTHEWS, License Number: 2318040, 1/24/2023 12:04:20 PM

Adjuster: TULLY, MARIANNE, (508) 946-6626 Evening

Insured:

ARDEN BUILDING

COMPANIES LLC

Owner Policy #:

CT50187VTOCAP2399A4

Claim #:

FQP7388001

Type of Loss:

Collision

Date of Loss:

01/10/2023 12:00 AM

Point of Impact:

Deductible:

21 Undercarriage

1000.00

Days to Repair:

Owner (Insured):

ARDEN BUILDING COMPANIES

505 NARRANGANSETT PARK

PAWTUCKET, RI 02861 (401) 727-3500 Business Inspection Location:

BMW OF WARWICK 1515 BALD HILL RD WARWICK, RI 02886-0000

Field

(401) 304-3222 Day

Appraiser Information:

Nrmatthe@travelers.com (401) 258-4576

Repair Facility:

BMW Of Warwick 1515 Baldhill rd Warwick, RI 02886 (401) 824-2399 Evening

VEHICLE

2020 BMW 5 Series M550i xDrive 4D SED 8-4.4L Turbocharged Gasoline Gasoline Direct Injection White

VIN:

WBAJS7C08LBN96032

Production Date:

07/2019

Interior Color:

License:

AE-400

35661

Black

State:

RI

Odometer: Condition:

Good

FM Radio

Exterior Color:

White

TRANSMISSION

Automatic Transmission

4 Wheel Drive

POWER

Power Steering Power Brakes

Power Windows Power Locks

Power Mirrors

Heated Mirrors Power Driver Seat

Power Passenger Seat Memory Package

DECOR Dual Mirrors Tinted Glass

Rear Power Sunshade

Air Conditioning

Intermittent Wipers Tilt Wheel Cruise Control Rear Defogger

Keyless Entry Alarm

Message Center

Steering Wheel Touch Controls

Telescopic Wheel Heated Steering Wheel Climate Control Navigation System Backup Camera Parking Sensors

Surround View Camera Intelligent Cruise

Stereo Search/Seek Auxiliary Audio Connection Premium Radio Satellite Radio SAFETY Drivers Side Air Bag Passenger Air Bag Anti-Lock Brakes (4) 4 Wheel Disc Brakes Front Side Impact Air Bags

Head/Curtain Air Bags Positraction Communications System Hands Free Device Blind Spot Detection

Electric Glass Sunroof

SEATS

Bucket Seats Leather Seats Heated Seats Rear Heated Seats Ventilated Seats

WHEELS

20" Or Larger Wheels

PAINT

Clear Coat Paint Metallic Paint

OTHER

Traction Control Stability Control Rear Spoiler

Signal Integrated Mirrors

Workfile ID:

FQP7388001 e801034d

Supplement of Record 1 with Summary

2020 BMW 5 Series M550i xDrive 4D SED 8-4.4L Turbocharged Gasoline Gasoline Direct Injection White

Console/Storage Wood Interior Trim

CONVENIENCE

Home Link
RADIO

AM Radio

Heads Up Display

Lane Departure Warning

ROOF

Xenon or L.E.D. Headlamps

Power Trunk/Liftgate

1/24/2023 12:04:30 PM

449865 | 1.8.09.04190

Page 2

Claim #: Workfile ID:

FQP7388001 e801034d

Supplement of Record 1 with Summary

2020 BMW 5 Series M550i xDrive 4D SED 8-4.4L Turbocharged Gasoline Gasoline Direct Injection White

Line			per	Description	Part Number	Qty	Extende		Labor	r	Paint
1	RADIATO	R SUPI	PORT				Price	\$			-
2		F	Repl Unde	r cover w/o M5 front	51757340168						
3		F		plate steering gear w/AWD	51757363731	1	137.9		0.3		
4	ELECTRI	CAL		godi nji	31/3/363/31	1	36.5	7	0.3		
5		S01 R	epl TPMS	sensor 433 mhz	26106007447						
6	EXHAUST	SYSTE			36106887147	1	119.6	1 m	Incl.		
7	*	R		xhaust assy rrwd of overter				m	Incl.	М	
8	WHEELS			en magellanus a vigle gas metalepia anno anno anno anno anno 1 anno 1. Na centra describerar y como esta describ	and the second production of the second seco		vertex true and the second			-	
9	*	S01 R	epl Wheel 9x20"	, alloy 20" style 668m,	36117855088	1	1,020.00	. m	0.3	М	
10	*	501 Re	epl Wheel 8x20"	alloy 20" style 668m,	36117855087	1	924.00	m	0.3	М	
11	#		Mount	Balance		2					
12	#			n Pilot 20"		2	70.00	X			
13	#			n Pilot 20" Rear		1	507.06		Incl.		
14	#		Alignm	*		1	518.82		Incl.		
15	FRONT SU	PENSI				1	169.85	X			
16		Re		er cntrl arm nut outer	22206707070	1007					
17	REAR SUSF	ENSIO		and the fact of th	33306787062	1	5.14				
18			O/H rr s	susp rt							
19	S	01 Rep		ckle w/o M5	222000000			m	5.1	М	
20	S	01		for Overlap	33306866336	1	1,044.87	m	Incl.		
21		Rep			22406000474				-0.8		
22		Rep		essmember 530i, 540i,	33406899174	1	351.60		Incl.		
		- 10	540d, M	550i	33316861201	1	2,124.43	m	8.2 M	1	
3		Rep	RT Traili	ng arm	33306893528	1	171.64		2		
4			Deduct f	or Overlap	0000003320	1	171.64	m	Incl.		
5	S0	1	Deduct f	or Overlap					-0.3 M	l	
6		Repl	RT Ft late	eral arm	33326867538	1	416.00		Incl.		
7		Repl	RT Rr lat	eral arm w/o M5	33326861126	1	416.88 r		Incl.		
3				or Overlap		1	196.17 r	n	Inci.		
9	SO:	l		or Overlap					-0.3 M		
)		Repl	RT Lower	cntrl arm w/o M5	33326875104	1	405 50		Incl.		
			Deduct fo		55525075107	1	485.50 n	n	Incl.		
	S01		Deduct fo	r Overlap					-0.3 M		
		Repl	RT Upper	cntrl arm	33326883340	1	E00 E2		Incl.		
			Deduct fo		30320005540	1	588.52 m)	Incl.		
	S01		Deduct for						-0.3 M		
#			clip			1	2		Incl.		
#			hex bolt			1	2.57		Incl.		
#			screw			2	30.20		Incl.		
						2	8.08		Incl.		

Claim #: Workfile ID:

FQP7388001 e801034d

Supplement of Record 1 with Summary

					SUBTOTALS	1	0,066.12	12.5	0
				.copui nit		1	26.10	Incl.	
2	#	S01		Repair kit	33316878218	1	51.11	Incl.	
1	*	S01	Repl	RT Susp crossmember bracket	22216070245	2		Incl.	
0		S01		Deduct for Overlap	37100007334	1	759.15 m	Incl.	
19		S01	Repl	RT Strut 4.4 liter	37106867354	1	65.68	Incl.	
18			Repl	RT Front brace	31106861142		121.22	Incl.	
1 7	*		Repl	RT Upper support	33506866272	1	7.86	Incl.	
46	#			hex		2		Incl.	
45	#			torx bolt 07119908024		1	6.31	Incl.	
14	#			hex bolt		1	12.03	Incl.	
43	#			hex bolt		1	18.45		
42	#			hex nut		3	19.14	Incl.	
				crescent		2	13.48	Incl.	
41	#			eccentric bolt		2	32.34	Incl.	
40	#			nut		1	3.80	Incl.	
39	#								

NOTES

Prior Damage Notes: none to be seen

ESTIMATE TOTALS

Catagoria				
Category	Basis		Rate	Cost \$
Parts			Ruce	
Body Labor	0.21	_		9,826.27
Mechanical Labor	-0.2 hrs	@	\$ 50.00 /hr	-10.00
Miscellaneous	12.7 hrs	@	\$ 170.00 /hr	2,159.00
Subtotal				239.85
Sales Tax				12,215.12
Total Cost of Repairs	\$ 9,826.27	@	7.0000 %	687.84
Deductible				12,902.96
Total Adjustments				1,000.00
			-	1,000.00
				11,902.96
Net Cost of Repairs				-

FQP7388001 e801034d

Supplement of Record 1 with Summary Workfile ID:

2020 BMW 5 Series M550i xDrive 4D SED 8-4.4L Turbocharged Gasoline Gasoline Direct Injection White

SUPPLEMENT SUMMARY

Line			Оре	Description	Part Number	Qty	Extended Price \$	Labor	Paint
Chang	ged Ite	ms				SON SOURS	Price \$		
7			Repl	Wheel, alloy 20" style 668m, 9x20"	36117855088	1	-987.00 m	-0.3 M	
9	*	S01	Repl	Wheel, alloy 20" style 668m, 9x20"	36117855088	1	<u>1,020.00</u> m	0.3 M	
8			Repl	Wheel, alloy 20" style 668m, 8x20"	36117855087	1	-898.00 m	-0.3 M	
10	*	501	Repl	Wheel, alloy 20" style 668m, 8x20"	36117855087	1	<u>924.00</u> m	0.3 M	
Added	Items				Section Residence	1000 Page			
4	ELECT	TRICAL							
5		S01	Repl	TPMS sensor 433 mhz	36106887147	1	119.61 m	Total	
19		S01	Repl	RT Knuckle w/o M5	33306866336	1	1,044.87 m	Incl.	
20		S01		Deduct for Overlap		-	1,044.87 111	Incl. -0.8	
25		S01		Deduct for Overlap					
29		S01		Deduct for Overlap				Incl.	
32		S01		Deduct for Overlap				Incl.	
35		S01		Deduct for Overlap				Incl.	
49		S01	Repl	RT Strut 4.4 liter	37106867354	1	759.15 m	Incl.	
50		S01		Deduct for Overlap	- 200007031	1	739.13 111	Incl.	
51	*	S01	Repl	RT Susp crossmember bracket	33316878218	1	51.11	Incl.	
52	#	S01		Repair kit		1	26.10	Incl.	
					SUBTOTALS		2,059.84	<u>Incl.</u> -0.8	0.0

NOTES

Prior Damage Notes: none to be seen

TOTALS SUMMARY

Pasis			
Basis		Rate	Cost \$
			2,059.84
-0.8 hrs	@	\$ 50.00 /hr	-40.00
			2,019.84
\$ 2,059.84	@	7.0000 %	144.19
			2 164 02
			2,164.03
			2,164.03
	-0.8 hrs \$ 2,059.84	-0.8 hrs @	-0.8 hrs @ \$ 50.00 /hr

Supplement of Record 1 with Summary

2020 BMW 5 Series M550i xDrive 4D SED 8-4.4L Turbocharged Gasoline Gasoline Direct Injection White

CUMULATIVE EFFECTS OF SUPPLEMENT(S)

Estimate 10,738.93 NICK MATTHEWS
Supplement S01 2,164.03 NICK MATTHEWS

Workfile Total: \$ 12,902.96

TOTAL ADJUSTMENTS: \$ 1,000.00

NET COST OF REPAIRS: \$ 11,902.96

All supplements must be pre-approved by Travelers.

Supplement repair charges may be subject to rejection unless approved by Travelers prior to repairs.

This instrument is a damage estimate only and not an acceptance of liability or authorization to repair.

Repair must be pre-authorized by the vehicle owner.

Vehicle owner maintains the right to repair vehicle at a repair facility of their choice.

Please present this estimate to the repair facility prior to repairs.

Necessary Information for Photograph and Video Estimates (READ CAREFULLY):

This estimate may have been completed based wholly or in part using photographs and/or video. Because of the use of photographs and video, this estimate may not be complete, as there could be hidden damage. You should provide this estimate to the shop of your choice prior to commencement of work. If your shop finds additional damages or undiscovered damages, Travelers will work with your repairer to assess the appropriate scope of work. Your shop is instructed in this estimate to contact Travelers through its supplement process and the damages they discover must be reviewed and approved prior to repairing the vehicle In the event that you are not repairing your vehicle and believe that our estimate does not account for all of your damages, please contact your Claim professional to discuss and address your concerns and options.

PURSUANT TO RHODE ISLAND LAW, THE CONSUMER HAS THE RIGHT TO CHOOSE THE REPAIR FACILITY TO COMPLETE REPAIRS TO A MOTOR VEHICLE; AND AN INSURANCE COMPANY MAY NOT INTERFERE WITH THE CONSUMER'S CHOICE OF REPAIRER.

FOR ANY VEHICLE THAT IS LESS THAN FORTY-EIGHT (48) MONTHS BEYOND THE DATE OF MANUFACTURE, RHODE ISLAND LAW ENTITLES THE VEHICLE OWNER TO ORIGINAL EQUIPMENT MANUFACTURER (OEM) PARTS IN THE REPAIR OF A MOTOR VEHICLE PART. THIS ESTIMATE WILL INDICATE IF/WHEN AFTERMARKET BODY PARTS ARE SPECIFIED.

Any person who knowingly presents a false or fraudulent claim for payment of a loss or benefit or knowingly presents false information in an application for insurance is guilty of a crime and may be subject to fines and confinement in prison.

FQP7388001 e801034d

Workfile ID:

Supplement of Record 1 with Summary

2020 BMW 5 Series M550i xDrive 4D SED 8-4.4L Turbocharged Gasoline Gasoline Direct Injection White

CUMULATIVE EFFECTS OF SUPPLEMENT(S)

Estimate

10,738.93

NICK MATTHEWS

Supplement S01

2,164.03

NICK MATTHEWS

Workfile Total:

12,902.96

TOTAL ADJUSTMENTS:

1,000.00

NET COST OF REPAIRS:

11,902.96

All supplements must be pre-approved by Travelers.

Supplement repair charges may be subject to rejection unless approved by Travelers prior to repairs.

This instrument is a damage estimate only and not an acceptance of liability or authorization to repair.

Repair must be pre-authorized by the vehicle owner.

Vehicle owner maintains the right to repair vehicle at a repair facility of their choice.

Please present this estimate to the repair facility prior to repairs.

Necessary Information for Photograph and Video Estimates (READ CAREFULLY):

This estimate may have been completed based wholly or in part using photographs and/or video. Because of the use of photographs and video, this estimate may not be complete, as there could be hidden damage. You should provide this estimate to the shop of your choice prior to commencement of work. If your shop finds additional damages or undiscovered damages, Travelers will work with your repairer to assess the appropriate scope of work. Your shop is instructed in this estimate to contact Travelers through its supplement process and the damages they discover must be reviewed and approved prior to repairing the vehicle In the event that you are not repairing your vehicle and believe that our estimate does not account for all of your damages, please contact your Claim professional to discuss and address your concerns and options.

PURSUANT TO RHODE ISLAND LAW, THE CONSUMER HAS THE RIGHT TO CHOOSE THE REPAIR FACILITY TO COMPLETE REPAIRS TO A MOTOR VEHICLE; AND AN INSURANCE COMPANY MAY NOT INTERFERE WITH THE CONSUMER'S CHOICE OF REPAIRER.

FOR ANY VEHICLE THAT IS LESS THAN FORTY-EIGHT (48) MONTHS BEYOND THE DATE OF MANUFACTURE, RHODE ISLAND LAW ENTITLES THE VEHICLE OWNER TO ORIGINAL EQUIPMENT MANUFACTURER (OEM) PARTS IN THE REPAIR OF A MOTOR VEHICLE PART. THIS ESTIMATE WILL INDICATE IF/WHEN AFTERMARKET BODY PARTS ARE SPECIFIED.

Any person who knowingly presents a false or fraudulent claim for payment of a loss or benefit or knowingly presents false information in an application for insurance is guilty of a crime and may be subject to fines and confinement in prison.

Supplement of Record 1 with Summary

2020 BMW 5 Series M550i xDrive 4D SED 8-4.4L Turbocharged Gasoline Gasoline Direct Injection White

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide ERE1952, CCC Data Date 01/17/2023, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2023 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

FQP7388001 e801034d

Supplement of Record 1 with Summary

2020 BMW 5 Series M550i xDrive 4D SED 8-4.4L Turbocharged Gasoline Gasoline Direct Injection White

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide ERE1952, CCC Data Date 01/17/2023, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2023 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

 $\label{eq:memoral} \begin{tabular}{ll} m=MOTOR & Mechanical component. & s=MOTOR & Structural component. & T=Miscellaneous & Taxed & Charge & Category. & T=Miscellaneous & Taxed & Charge & Category. & T=Miscellaneous & T=Misce$

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.